



U.S. DEPARTMENT OF THE INTERIOR
U.S. Geological Survey

DISCHARGE MEASUREMENT AND
GAGE INSPECTION NOTES

Inspection

Insp by: KEK

SVMobile ver. 1.0.2 Stylesheet ver. 1.4.1

Site Visit Summary

357002 - West Canal blw Page Springs Dam, Malheur NWR

Date: 2022-04-12


Start Time: 11:36:00 PST

End Time:

Party: KEK

Weather: mostly cloudy, very cold, flurries, moderate wind, swirling/variable

Site Visit Tasks

Discharge Measurement: 

Control Inspection: 

GZF Inspection: 

Comment:

CalPoly Measurement 0.16 x 6.5ft = 1.17cfs. Leakage below dam board crest.