



**U.S. DEPARTMENT OF THE INTERIOR
U.S. Geological Survey**

SITE VISIT NOTES

Inspection

Insp by: SW

SVMobile ver. 1.0.2 Stylesheet SWAMI_SS1 ver. 1.5.1

Site Visit Summary

357003 - Blitzen blw Page Springs Dam, Malheur NWR

Date: 2025-06-23

Start Time: 11:55:00 PST

End Time:

Party: SW

Comment:

Measurement by refuge staff. FT2 file in PDT. Discharge 92.727cfs Staff gage 0.64ft