



U.S. DEPARTMENT OF THE INTERIOR
U.S. Geological Survey

SITE VISIT NOTES

Inspection

Insp by: SW

SVMobile ver. 1.0.2 Stylesheet SWAMI_SS1 ver. 1.5.1

Site Visit Summary

357003 - Blitzen blw Page Springs Dam, Malheur NWR

Date: 2025-08-06

Start Time: 12:46:00 PST

End Time:

Party: SW

Comment:

Measurement by refuge staff. FT2 file in PDT. Q: 56.2903cfs. Staff gage 0.32ft at 1333