



U.S. DEPARTMENT OF THE INTERIOR
U.S. Geological Survey

SITE VISIT NOTES

Inspection

Insp by: SW

SVMobile ver. 1.0.2 Stylesheet SWAMI_SS1 ver. 1.5.1

Site Visit Summary

357005 - Blitzen blw Sodhouse Dam, Malheur NWR

Date: 2025-08-18

Start Time: 15:50:00 PST

End Time: 15:50:02 PST

Party: SW

Recorder record removed.

Comment:

Measurement by refuge staff. Discharge 79.97cfs, staff 3.58ft at 1744PST