



**U.S. DEPARTMENT OF THE INTERIOR
U.S. Geological Survey**

SITE VISIT NOTES

Inspection

Insp by: SW

SVMobile ver. 1.0.2 Stylesheet SWAMI_SS1 ver. 1.5.1

Site Visit Summary

357005 - Blitzen blw Sodhouse Dam, Malheur NWR

Date: 2025-09-17

Start Time: 14:51:00 PST

End Time:

Party: SW

Comment:

Measurement by refuge staff. Discharge 70.5978cfs, 3.48ft at 1510PST.